



LEARNING FROM INCIDENTS

INVESTIGATION REPORT

GROSVENOR MINE

Metallurgical Coal

Incident Number: IN.00211941

Classification: *DNRM HPI*

Incident Title: CH₄ Exceedance LW103

Incident Date: 7 November 2019

Report Date: 20 November 2019

Learning from Incidents Investigation Report

1	Investigation Team Members	3
2	Key Witnesses	3
3	Methodology and Tools Used	3
4	Description of Incident	4
4.1	Geotechnical Assessment	4
5	Critical Control Failure	6
6	Event Factors	7
7	Findings and Conclusions	7
8	Preventative Actions / Recommendations	7
9	Test for Effectiveness	7
10	Investigation Report Sign –Off	8
11	APPENDIX: Sequence of Events	9
12	APPENDIX: Control Analysis	10
13	APPENDIX: Change Analysis	10
14	APPENDIX: Why Tree Analysis	11
15	APPENDIX: Incident report	12
16	APPENDIX: Event Citect Trend	14
17	APPENDIX: Gas Make Calculation	15
18	APPENDIX: Stratigraphy	16

20191107-HPI-CH4 Exceedance LW103-LFI	Original Issue Date:	Version:	1	Printed: 09/12/2019 Page 2 of 16
	06/12/2019	Date of Issue:	06/12/2019	
PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED AND DEEMED VALID ONLY ON THE DAY OF PRINTING				

1 INVESTIGATION TEAM MEMBERS

Name	Role	Designation
Logan Mohr	Tech Services Manager	Sponsor
Hayden Hearne	Ventilation and Gas Superintendent	Investigation Lead / Facilitator
Ray Kostowski	Technical Services Superintendent	Technical / Operational Expert
Stephen Giese	Geology and Geotechnical Superintendent	Technical / Operational Expert
Adam Maggs	ERZ Controller	Technical / Operational Expert

2 KEY WITNESSES

List of Key Witnesses	
Name	Designation
Adam Maggs	ERZ Controller

3 METHODOLOGY AND TOOLS USED

An investigation has been conducted in accordance with the Anglo American investigation methodology known as the Learning from Incidents model, supported by various investigative and analytical tools.

The analysis tools used for this investigation are:

Analysis Tool	Attached as Appendix if applicable - Yes/No
Time Series Events Chart	Yes – mandatory tool
Control Analysis	Yes
Behaviour Analysis	No
Change Analysis	Yes
Why Analysis	Yes

4 DESCRIPTION OF INCIDENT

On Thursday the 7th of November during normal production, the shearer on the LW103 face was travelling to the MG (cutting bi-directional) when at roof support #9, a floor blower became active at roof supports #22 and #55 after mining past the area and advancing the face. The tailgate drive sensors at 03:04 went above 2.0% tripping face power. The methane monitor in the TG roadway peaked at 2.73% at 03:08am.

The methane calculated to have released into the mine's general body atmosphere was approximately 1,504m³ after 2 hours before returning to normal background levels.

4.1 Geotechnical Assessment

Floor fracturing behind/underneath a longwall face has not been studied extensively due to the operational limitations surrounding such research. No specific study has been performed for Grosvenor to date that identifies the extent of potential floor fracturing; as such a literature review has been performed to identify how deep floor fractures can reasonable extend under a longwall retreat scenario.

A paper by Bai & Tu, 2019 titled *A General Review on Longwall Mining-Induced Fractures in Near-Face Regions* discusses this issue in some detail. This paper discussed that field observations indicated that there are two main types of primary floor failure, namely shear failure along bedding planes in the floor which causes horizontal fractures, and the formation of subvertical fractures parallel to the longwall face ahead of the longwall shield supports. Observations also indicated that vertical fractures play a dominating role within the failure zones, with numerical simulations confirming these observations. These vertical fractures are what can act as a conduit for gas/water to flow through from underlying reservoirs.

This paper, which primarily focuses on longwall operations in China, discusses that many operations there work above confined aquifers, hence determining failure scope within the floor is an important factor. An empirical formula was developed to predict the depth of 'water-conducting failure zones' for Chinese operations, however it is proposed that this is applicable as well for Grosvenor to provide indicative values of depth of fracturing that may provide a conduit for gas flow.

This empirical formula is as follows:

$$H_f = 0.303L_x^{0.8}$$

Where:

H_f is the depth of fracturing into the floor that can act as a hydraulic conduit

L_x is the width of the longwall panel.

Using this relationship for Grosvenor, the approximate depth of fracturing is 29m. It is acknowledged that this relationship is an empirical one derived from longwall operations in China, however the database contains cases with a varying range of cover depths (103m to 560m), hence can be used to provide a baseline value.

In addition to this, there are varying models that can be used for the prediction of the degree of gas emissions from overlying and underlying seams in a longwall operation. One such model is the Flugge model, as shown below.

20191107-HPI-CH4 Exceedance LW103-LFI	Original Issue Date: 06/12/2019	Version:	1	Printed: 12/10/2019 Page 4 of 16
		Date of Issue:	06/12/2019	
PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED AND DEEMED VALID ONLY ON THE DAY OF PRINTING				




Figure 1 - Flugge Model for Predicting Gas Emission Degrees

This model suggests that the deepest below the floor that a seam may emit emissions from is 40m. This is in a similar range to the value derived from the empirical model by Bai & Tu for estimating floor fracturing creating a hydraulic conduit for gas to flow from underlying seams. As such it can be concluded that seams up to 40m below the seam floor should be considered for potential to emit gas into the LW working area/goaf. In the zone for this LFI, this would include the GML and the Harrow Creek Lower Measures (see Appendix: Stratigraphy).

It is important to note that geological structures can create localized anomalous conditions that may lead to a zone of fracturing that can act as a conduit for gas emissions, or the fault plane itself can act as a conduit. The figure below shows the LW face at the time of the incident and highlights the major structure in the area.

20191107-HPI-CH4 Exceedance LW103-LFI	Original Issue Date: 06/12/2019	Version:	1	Printed: 12/10/2019 Page 5 of 16
		Date of Issue:	06/12/2019	
PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED AND DEEMED VALID ONLY ON THE DAY OF PRINTING				




Figure 2 – Geological Conditions During Event

This section shows that the face was not affected by any geological discontinuities at the time of the event, with the only major structure within the area located approximately 80m outbye in the maingate at the time of the event. This information suggests the this event was not caused by a localized geological structure.

In addition to this, the diagram above also shows gas compliance holes within the area of the event, however none of these holes took samples of the underlying seams below the GM.

5 CRITICAL CONTROL FAILURE

(List any identified critical control failures that contributed to this event)

What / which critical controls failed? (List CT number)	Nil
---	-----

6 EVENT FACTORS

Review data from LFI Tools and record into the identified **factors** below. This data is required for the Enablon summary.

Individual Factors	Nil individual factors identified
Workplace Factors	LTA pre-drainage program in lower seam(s)
Organisational Factors	Gas make (SGE) greater than expected in excess of system capacity (Floor release) Less than adequate methane pre-drainage / recovery / dilution

7 FINDINGS AND CONCLUSIONS

Through the LFI Investigation process, the following were found to have contributed to the unwanted event:

- The floor blowers located at #22 and #55 roof support released approximately 1,504m³ after 2 hours.
- Mining past the area stimulated the release of gas into the mine atmosphere from a reservoir from beneath the target mining seam.
- The release of gas was substantial enough to trip power to the face and exceed 2.5% in the tailgate return.
- Underlying seams up to 40m below the GM seam should be considered for the potential to emit gas into the longwall working section

8 PREVENTATIVE ACTIONS / RECOMMENDATIONS

The following key actions were identified to prevent recurrence and have been assigned as detailed below in Enablon.

Task Description	Hierarchy of Control	Task Assignee	Due Date	Task ID
Trial of GML holes underway in LW105 to target immediate Gas Reservoir in floor horizon.	Engineering	Hayden Heame	05/02/2020	TS.01166665
Conduct a detailed investigation to try and identify the source of the methane	Administration	Hayden Heame	05/02/2020	TS.01166669

9 TEST FOR EFFECTIVENESS

Post Implementation Action Plan

Test of effectiveness is to be done to ensure that the above actions to prevent recurrence have worked as intended. (Nominally scheduled 3,6 or 12 months after completion of preventative action plan)

Enablon Task No.	Action Description	Responsible Person	Due Date	Completed Date
TS.01166671	Review effectiveness of action close out from Incident INC.00211941	Logan Mohr	08/05/2020	

20191107-HPI-CH4 Exceedance LW103-LFI	Original Issue Date: 06/12/2019	Version:	1	Printed: 12/10/2019 Page 7 of 16
		Date of Issue:	06/12/2019	
PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED AND DEEMED VALID ONLY ON THE DAY OF PRINTING				



10 INVESTIGATION REPORT SIGN –OFF

The Incident Investigation Team submits this report as a true reflection of the information gathered. To maximize the preventive potential of the investigation report, the findings, conclusions and learning's of the report should be distributed as appropriate.

Acceptance of Final Report for Management Sign Off

Department Superintendent		
Name	Signature	Date
Hayden Heame	[REDACTED]	5 12 19

MEM/EEM Sign Off (if applicable)

Electrical Engineering Manager or Mechanical Engineering Manager (tick)		
Name	Signature	Date

Management Sign Off

Department Manager		
Name	Signature	Date
Logan Mohr	[REDACTED]	5/12/19
SHE Manager		
Name	Signature	Date
KATE BACHMANN SHE MANAGER	[REDACTED]	5 12 19
Underground Mine Manager		
Name	Signature	Date
WALTER MICHAEL	[REDACTED]	5/12/2019
General Manager		
Name	Signature	Date
ROBERT NIVERT	[REDACTED]	6/12/19.
Head of Operations		
Name	Signature	Date
G. S. BRITTON	G BRITTON	10/12/19.

20191107-HPI-CH4 Exceedance LW103-LFI	Original Issue Date: 06/12/2019	Version:	1	Printed: 12/10/2019 Page 8 of 16
		Date of Issue:	06/12/2019	
PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED AND DEEMED VALID ONLY ON THE DAY OF PRINTING				



11 APPENDIX: SEQUENCE OF EVENTS

Date	Time	Event or Condition
06/11/2019	20:00	Start of Night Shift (communications and travel)
	21:40	Production
7/11/2019	12:20 – 12:30	Production Delay – Removed structure
	12:30-02:00	Production
	02:00-02:10	TG Inspection
	02:10-02:15	Production
	02:15-02:20	Delay: BSL Pilot Fault
	02:20-03:00	Production
	03:04	Production stoppage due to tailgate drive sensor >2.0% CH4 – Lost Face Power
7/11/2019	03:08	EVENT: CH4 >2.5% in Tailgate Return Outbye CH Sensor Peaks at 2.73%
7/11/2019	Post Incident	ERZ Controller informed UM, UM informed UMM
		A floor blower was found at #22 and #55 Roof Support
		Setup Venturis @ #22 Roof Support
	04:07	Power restored to face

20191107-HPI-CH4 Exceedance LW103-LFI	Original Issue Date: 06/12/2019	Version:	1	Printed: 12/10/2019 Page 9 of 16
		Date of Issue:	06/12/2019	
PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED AND DEEMED VALID ONLY ON THE DAY OF PRINTING				

12 APPENDIX: CONTROL ANALYSIS

From the description of what happened and the sequence of events, what were the absent or failed controls?

Consider:

- What would have prevented the incident?
- What would have decreased the severity of the incident?

Unwanted Event: Methane in excess of 2.5%				
Hazard: Elevated methane				
Absent or Failed control and support systems	How did they perform?	Why did they fail or were absent?	Outcome of failed or absent controls and support systems.	Site critical control Yes or No?
Gas Pre-drainage Process	Failed	Isolated region of gas relieving into mine atmosphere after induced stresses	Methane reported to general body atmosphere greater than acceptable limits from adjacent seam/strata	No

APPENDIX: CHANGE ANALYSIS

Change is anything which alters the planned operating process or system. The Change Analysis technique identifies how new risks which were a direct result of change in the work environment were managed prior to the incident occurring.

Basic Methodology: -


- Describe the situation before the change was made
- Describe situation at the time incident occurred
- Conduct a gap analysis by comparing steps 1 & 2
- Identify the impact of the gap

Normal Practice	Situation or practice at the time of the incident	Gap (difference)	Impact of Difference
Pre-drainage system	Pre-drainage of GM and P Seam	Floor Blowers connecting to reservoir below GM Seam	General body concentrations of CH ₄ exceeding 2.0% at Tailgate drive and 2.5% in tailgate roadway
Mine ventilation system	Normal operation	Increased gas make – Floor blower	General body concentrations of CH ₄ exceeding 2.5% in tailgate roadway

20191107-HPI-CH4 Exceedance LW103-LFI	Original Issue Date: 06/12/2019	Version:	1	Printed: 12/10/2019 Page 10 of 16
		Date of Issue:	06/12/2019	
PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED AND DEEMED VALID ONLY ON THE DAY OF PRINTING				



13 APPENDIX: WHY TREE ANALYSIS





14 APPENDIX: INCIDENT REPORT

Hazard & Incident Report Form
31388

Enablon ID No. 211941 **DNRM HPI**

To be completed by reporting person with assistance from Supervisor (for Surface incidents) or ERZ Controller (for UG incidents)
ALL Sections of this form are mandatory unless marked.

Title of Hazard / Incident: Gas Exceedance in tailgate from Blowers											
Date occurred: 7 / 11 / 19	Time: 3:05pm										
Classification: Hazard <input checked="" type="checkbox"/> Safety <input type="checkbox"/> Material Losses / Damage / Business Interruption <input type="checkbox"/> Legal / Regulatory <input checked="" type="checkbox"/> Environment <input type="checkbox"/> Social / Community <input type="checkbox"/> Impact on Reputation <input type="checkbox"/> Health / Fitness <input type="checkbox"/> Workplace Exposure <input type="checkbox"/>											
Department: <input type="checkbox"/> Outbye <input type="checkbox"/> Development <input type="checkbox"/> Longwall <input checked="" type="checkbox"/> Compliance <input type="checkbox"/> Tech Services <input type="checkbox"/> Seamgas <input type="checkbox"/> SHE <input type="checkbox"/> Business Impovement <input type="checkbox"/> Human Resources <input type="checkbox"/> Commercial / Supply Chain <input type="checkbox"/> Maintenance / Engineering <input type="checkbox"/> Other <input type="checkbox"/>											
Specific Location: TG Roadway & Longwall Face											
Reported By: Adam Maggs											
Key Person(s) Involved: Adam Maggs											
Others Involved: (e.g. Witnesses)											
Equipment Involved: TG RTW Sensor	ERZC / Supervisor: Adam Maggs										
Crew: A	Contractor Group:										
Shift Length: 12	Hours into Shift: 8										
Consecutive days worked: 6											
Incident Description: Whilst cutting into Mangate Power dropped of on inspection found 2 Blowers @ 22# & 55# which cause an increase in gas on face & spike TG RTW Sensor 2.7890 cfm											
Diagram (Attach additional notes if required):											
Immediate Direct Cause: Blowers in coal	Mechanism: Gas										
Immediate Corrective Actions Taken: Investigated, Reported & Setup Venturices @ 22#											
Refer to attached Grosvenor Risk Matrix for below:											
Actual Consequence: Not Applicable for Hazards	<table border="1" style="width: 100%; text-align: center;"> <tr> <td>Insignificant <small>(1hr. abs. conv, damage <0.01% annual revenue etc)</small></td> <td>Minor <small>(med. health, damage 0.01-0.1% annual revenue)</small></td> <td>Moderate <small>(lost time injury, damage 0.1-1.0% annual revenue)</small></td> <td>High <small>(permanent disability, fatality, Anglo HPI)</small></td> <td>Major <small>(numerous permanent disabilities, fatality, Anglo HPI)</small></td> </tr> <tr> <td>Insignificant <small>(1hr. abs. conv, damage <0.01% annual revenue etc)</small></td> <td>Minor <small>(med. health, damage 0.01-0.1% annual revenue)</small></td> <td>Moderate <small>(lost time injury, damage 0.1-1.0% annual revenue)</small></td> <td>High <small>(permanent disability, fatality, Anglo HPI)</small></td> <td>Major <small>(numerous permanent disabilities, fatality, Anglo HPI)</small></td> </tr> </table>	Insignificant <small>(1hr. abs. conv, damage <0.01% annual revenue etc)</small>	Minor <small>(med. health, damage 0.01-0.1% annual revenue)</small>	Moderate <small>(lost time injury, damage 0.1-1.0% annual revenue)</small>	High <small>(permanent disability, fatality, Anglo HPI)</small>	Major <small>(numerous permanent disabilities, fatality, Anglo HPI)</small>	Insignificant <small>(1hr. abs. conv, damage <0.01% annual revenue etc)</small>	Minor <small>(med. health, damage 0.01-0.1% annual revenue)</small>	Moderate <small>(lost time injury, damage 0.1-1.0% annual revenue)</small>	High <small>(permanent disability, fatality, Anglo HPI)</small>	Major <small>(numerous permanent disabilities, fatality, Anglo HPI)</small>
Insignificant <small>(1hr. abs. conv, damage <0.01% annual revenue etc)</small>	Minor <small>(med. health, damage 0.01-0.1% annual revenue)</small>	Moderate <small>(lost time injury, damage 0.1-1.0% annual revenue)</small>	High <small>(permanent disability, fatality, Anglo HPI)</small>	Major <small>(numerous permanent disabilities, fatality, Anglo HPI)</small>							
Insignificant <small>(1hr. abs. conv, damage <0.01% annual revenue etc)</small>	Minor <small>(med. health, damage 0.01-0.1% annual revenue)</small>	Moderate <small>(lost time injury, damage 0.1-1.0% annual revenue)</small>	High <small>(permanent disability, fatality, Anglo HPI)</small>	Major <small>(numerous permanent disabilities, fatality, Anglo HPI)</small>							
Potential Consequence:											
Has the hazard, defect or incident been effectively controlled on shift? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>											
if not, why not?											

GM1780 30 PRINT

20191107-HPI-CH4 Exceedance LW103-LFI	Original Issue Date: 06/12/2019	Version: 1	Printed: 09/12/2019
		Date of Issue: 06/12/2019	Page 12 of 16

PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED AND DEEMED VALID ONLY ON THE DAY OF PRINTING



Enablon ID No.

Hazard & Incident Report Form



Peoples Behaviours:	Timeline
	2:00 Cutting
	3:03 Loss of Power
Environment: Gas Exceedance	3:13 Inspected third Blower 22ft & 55ft
	3:20 Reportal.
Equipment: Sensors,	
Procedures: Legislative HFI	

Additional Actions to prevent reoccurrence: (ERZ Controller/ Supervisor to complete)

Action Description	By Whom	Action Due (date)	Enablon ID #
Setup Venturics	Deputy	---	---
COMPLETE LFI	H. HEARNS	TS.01146930	
		TS.01146932	
		TS.01146933	
Is a Banner Alert required to be issued? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		TS.01146934	
If yes, which Banner Alert: Green <input type="checkbox"/> Orange <input type="checkbox"/> Red <input type="checkbox"/>	H. Hearne	TS.01146935	

Incident Sign Off:

Person Reporting:	Date: 7/11/19	Supervisor (for Surface incidents) ERZ Controller (for UG incidents)	Date: 7/11/19
Name: Adam Mags		Name: Adam Mags	
Signature: [Redacted]		Signature: [Redacted]	


Verification Sign Off:

Undermanager	Name: AKRUSE	Signature: [Redacted]	Date: 7/11/19
Superintendent/ Manager	Name: H. HEARNS	Signature: [Redacted]	Date: 7/11/19
Entered into Enablon by (Name): J. Conroy		Signature: [Redacted]	Date: 8/11/19



15 APPENDIX: EVENT CITECT TREND

12 Hour Period




20191107-HPI-CH4 Exceedance LW103-LFI	Original Issue Date: 06/12/2019	Version:	1	Printed: 09/12/2019 Page 14 of 16
		Date of Issue:	06/12/2019	
PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED AND DEEMED VALID ONLY ON THE DAY OF PRINTING				



16 APPENDIX: GAS MAKE CALCULATION

Baseline CH4 before event	0.73				
Tailgate CH4					
Start of Event	7/11/2019 3:04				
End of Event	7/11/2019 5:08				
Peak CH4 through fan (%)	2.73				
Total CH4 Released (m3)	1,504				



20191107-HPI-CH4 Exceedance LW103-LFI	Original Issue Date:	Version:	1	Printed: 09/12/2019
	06/12/2019	Date of Issue:	06/12/2019	Page 15 of 16

PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED AND DEEMED VALID ONLY ON THE DAY OF PRINTING

17 APPENDIX: STRATIGRAPHY

