

Cooney, Joanne

From: Penrose, Alisha
Sent: Wednesday, 15 April 2020 11:55 AM
To: Grosvenor Mine Record
Subject: FW: Completed Mining incident report No. 144513 (30 - High potential no lost time [nmsf: 35])
Categories: Red Category

For saving to mine record.

Thanks Jo!

Regards

Alisha Penrose, alisha.penrose@dnrm.qld.gov.au M + [REDACTED]

From: MIRAdministration@dnrme.qld.gov.au <MIRAdministration@dnrme.qld.gov.au>
Sent: Wednesday, April 15, 2020 11:13 AM
To: MIRAdministration@dnrme.qld.gov.au; mirmackay@dnrm.qld.gov.au; Penrose, Alisha
 <Alisha.Penrose@dnrm.qld.gov.au>
Subject: Completed Mining incident report No. 144513 (30 - High potential no lost time [nmsf: 35])

This message originated outside Anglo American

Type of incident

Incident report number: 144513

Recipients: alisha.penrose@dnrm.qld.gov.au and MIRAdministration@dnrme.qld.gov.au

- 1 **Incident type:** 30 - High potential no lost time [nmsf: 35]
- 2 **Summary/title of incident**
 CH4 exceedance LW104

Incident Classification:	Code: 114 - Presence of gas [nmsf: 3827]
Breakdown:	Code: Other and unspecified agencies [nmsf: 2844]
Sub-Breakdown:	Code: Other and not specified agencies [nmsf: 2890]
Breakdown Class:	Code: Other agencies, not elsewhere classified [nmsf: 3188]
Detailed Classification:	Code: Other agencies, not elsewhere classified [nmsf: 3766]
Compensation ID: 999999	
Mechanism:	Code: Heat, electricity and other environmental factors [nmsf: 2789]
Sub-Mechanism:	Code: Exposure to other and unspecified environmental factors [nmsf: 2821]
- 3 **Previously notified:** Yes
Date: 20/03/2020

Mine details

- 4 Mine/quarry name Grosvenor Coal Mine Code: M02976 Old Code:
- 5 Mine type: coalUnderground
- 6 Company contact: Wouter Niehaus
Phone: [REDACTED]
- 7 Where in the mine did the incident occur? LW104 TG Code: 503 - Coal face-2nd workings [nmsf: 27]
Surface or underground? underground

Incident details

- 8 Date of incident: 20/03/2020
- 9 Time of incident: 14 40 (24 hr clock)
- 10 Time shift started: 09 30
Shift duration: 12 00
No. of complete shifts/day worked prior to accident: 2
No. of days in shift cycle: 14
No. of days rostered off prior to starting current shift cycle: 7
Total hrs worked in 24 hr period prior to accident, inc travel time: 12
Travel Time: 00 00
Rostered Travel Time: 00 15
Roster Pattern: 7/7
- 11 Date of first full working day lost:
- 12 Primary equipment/tool involved in incident: longwall shearer Code: 111 - Longwall shearer [nmsf: 3881]
- 13 Describe exactly how did the incident occur:
20/03/2020 14:40 CH4 @ LW104 TG IB #38 sensor exceeded 2.5%. Shearer had stopped for 20 minutes due to the CH4 inhibit from LW104 TG IB #38 sensor. GMS11 GR04V002A 20/03/2020 13:45 Differential pressure @ 14Kpa with flow @ 2209l/s – this is not normal goaf hole behavior.
- 14 What hazards have been identified from this incident:
Elevated Methane
- Code: 112 - Flammable liquids/gases

Injured person details

- 15-21 Questions 15 through 22 not required for 'High potential no lost time' incidents
- 23 Description of personal damage:

Is this a permanent incapacity?

Incident causes

- 24 What happened leading up to the injury/incident/disease?
Organisational
Nil
- Codes 122 - No org. factor involved

<p>Task/environment conditions</p> <p>P seam gas drainage not completed to proposed strategy to allow LW104 unconstrained production from gas delays. Lateral hole drilling experiencing numerous delays when drilling through fault planes.</p>	<p>Codes 321 - Other task/environment factor</p>
<p>Individual/team actions</p> <p>Nil</p>	<p>Codes 222 - No ind./team factor involved</p>
<p>Absent or failed defences</p> <p>Nil</p>	<p>Codes 422 - No absent/failed defence factor involved</p>

Preventative action

25 Give details of any control measures/actions being considered and/or implemented to prevent recurrences

P seam drainage strategy for each LW block to design & complete prior to LW production phase. Investigate Citect alarm & messaging system failure and implement controls to prevent a re-occurrence. Document the IMT process currently used onsite for acknowledgement of action allocation & understanding. Investigate modifications to the goaf skid flame arrestor to allow the current fleet to be maintained whilst remaining in service. Ventilation network for LW tailgates to assess for risk of failure when using dual return roadways. Amend the gas drainage TARP to add guidance for high flow goaf hole maintenance practices.

Date: 15/04/2020

Your full name: Alisha Penrose

Position: Health & Safety Officer

Email: alisha.penrose@...

Office use

Inspector/inspection officer: _____

Signed: _____

Entered by: _____

User IP address: 172.18.4.56

User agent: Mozilla/5.0 (Windows NT 10.0; Win64; x64) AppleWebKit/537.36 (KHTML, like Gecko) Chrome/80.0.3987.163 Safari/537.36

Email address: alisha.penrose@...

Submitted Date/Time: 15/04/2020 11:09:57

The information in this email together with any attachments is intended only for the person or entity to which it is addressed and may contain confidential and/or privileged material. There is no waiver of any confidentiality/privilege by your inadvertent receipt of this material.

Any form of review, disclosure, modification, distribution and/or publication of this email message is prohibited, unless as a necessary part of Departmental business.

If you have received this message in error, you are asked to inform the sender as quickly as possible and delete this message and any copies of this message from your computer and/or your computer system network.
