

Cooney, Joanne

From: Penrose, Alisha
Sent: Friday, 22 May 2020 5:15 PM
To: Grosvenor Mine Record
Subject: FW: Completed Mining incident report No. 144850 (30 - High potential no lost time [nmsf: 35])

Categories: Red Category

For Mine Record Please ladies 😊

Regards

Alisha Penrose, alisha.penrose@dnrm.qld.gov.au M [REDACTED]

From: MIRAdministration@dnrme.qld.gov.au <MIRAdministration@dnrme.qld.gov.au>
Sent: Friday, May 22, 2020 5:08 PM
To: MIRAdministration@dnrme.qld.gov.au; mirmackay@dnrm.qld.gov.au; Penrose, Alisha <Alisha.Penrose@dnrm.qld.gov.au>
Subject: Completed Mining incident report No. 144850 (30 - High potential no lost time [nmsf: 35])

This message originated outside Anglo American

Type of incident

Incident report number: 144850

Recipients: alisha.penrose@dnrm.qld.gov.au and MIRAdministration@dnrme.qld.gov.au

- 1 **Incident type:** 30 - High potential no lost time [nmsf: 35]

- 2 **Summary/title of incident**
 Exceedance LW104 1.54AM 21APR2

Incident Classification:	Code: 114 - Presence of gas [nmsf: 3827]
Breakdown:	Code: Other and unspecified agencies [nmsf: 2844]
Sub-Breakdown:	Code: Other and not specified agencies [nmsf: 2890]
Breakdown Class:	Code: Other agencies, not elsewhere classified [nmsf: 3188]
Detailed Classification:	Code: Other agencies, not elsewhere classified [nmsf: 3766]
Compensation ID: 999999	
Mechanism:	Code: Chemicals and other substances [nmsf: 2790]
Sub-Mechanism:	Code: Other and unspecified contact with chemical or substance [nmsf: 2825]

- 3 **Previously notified:** Yes
Date: 21/04/2020

Mine details

- 4 Mine/quarry name Grosvenor Coal Mine Code: M02976 Old Code:
- 5 Mine type: coalUnderground
- 6 Company contact: Wouter Niehaus
Phone: [REDACTED]
- 7 Where in the mine did the incident occur? LW104 TG S243A Code: 503 - Coal face-2nd workings [nmsf: 27]
Snesor TG Shield
Surface or underground? underground

Incident details

- 8 Date of incident: 21/04/2020
- 9 Time of incident: 01 54 (24 hr clock)
- 10 Time shift started: 21 30
Shift duration: 12 00
No. of complete shifts/day worked prior to accident: 5
No. of days in shift cycle: 14
No. of days rostered off prior to starting current shift cycle: 7
Total hrs worked in 24 hr period prior to accident, inc travel time: 12
Travel Time: 00 00
Rostered Travel Time: 00 00
Roster Pattern: 7/7
- 11 Date of first full working day lost:
- 12 Primary equipment/tool involved in incident: longwall Code: 119 - Longwall-other equipment [nmsf: 3884]
- 13 Describe exactly how did the incident occur:
After first event at 12:55am the gas had dropped and steadied, the shearer was re-powered and commenced cutting at 1:53am. The S243A sensor went over again at 1:54am and peaked at 2.55%. Shearer had only moved from #118 – #134. After the event the butchers curtain at 145# was altered to get a more even flow of air in back walkway. A brattice wing was installed after the first event to limit the impact of the goaf on the TG area.
- 14 What hazards have been identified from this incident:
Methane general body atmosphere exceeding legislated limits
Code: 124 - Noxious liquids/gases

Injured person details

- 15-21 Questions 15 through 22 not required for 'High potential no lost time' incidents
- 23 Description of personal damage:

Is this a permanent incapacity?

Incident causes

- 24 What happened leading up to the injury/incident/disease?
Organisational | Codes 121 - Other org. factor

Gas make (SGE) greater than expected in excess of system capacity

Task/environment conditions

Codes 321 - Other task/environment factor

Inadequate ventilation control measures around tg drive area

Individual/team actions

Codes 221 - Other ind./team factor

Venturis within TG area had been altered

Absent or failed defences

Codes 421 - Other absent/failed defence factor

NA

Preventative action

25 Give details of any control measures/actions being considered and/or implemented to prevent recurrences

Conduct trial of alternate Ventilation configurations in TG area and report to LW team upon completion Update GRO-4801-STD-Longwall Standard Area Management System based on Report from trial Ventilation arrangements from Vent and Gas Super Insert T-piece on air line supplying venturi at TG end of LW and tag (Do not use unless directed by ERZ Controller)

Date: 22/05/2020

Your full name: Alisha Penrose

Position: Health & Safety Officer

Email: [alisha.penrose](mailto:alisha.penrose@...)

Office use

Inspector/inspection officer: _____

Signed: _____

Entered by: _____

User IP address: 172.18.4.56

User agent: Mozilla/5.0 (Windows NT 10.0; Win64; x64) AppleWebKit/537.36 (KHTML, like Gecko) Chrome/81.0.4044.138 Safari/537.36

Email address: [alisha.penrose](mailto:alisha.penrose@...)

Submitted Date/Time: 22/05/2020 17:04:52

The information in this email together with any attachments is intended only for the person or entity to which it is addressed and may contain confidential and/or privileged material. There is no waiver of any confidentiality/privilege by your inadvertent receipt of this material.
Any form of review, disclosure, modification, distribution and/or publication of this email message is prohibited, unless as a necessary part of Departmental business.
If you have received this message in error, you are asked to inform the sender as quickly as possible and delete this message and any copies of this message from your computer and/or your computer system network.
