



GROSVENOR COAL MINE
PRO-Mine Emergency Response System

20.1.12. Appendix 11: ERT Debrief Form

Debrief Officer:

Role:

Date/Time of Debrief:

Date of Emergency:	6/5/20	Time Emergency Started:		Time Emergency Finished:	
Type of Emergency:	LW FIRE				
Location of Emergency:	104				
Name:	A EHEM				
Crew/Department:	LW Bull Gang				
Work location:	O/B 34 c/t				
Role in ERT:	Drove injured out				
Time Notified of Emergency:	-				
How Notified:	-				
Time Your Response Started:	-				
No. of responders in ERT:					
Breakdown of Emergency					
Time	Description				
	AT 34 c/t O/B thought there was a goaf fall - went to investigate and was met at the U/m/c By Bo Lacey and told to get the vehicle ready Drove out.				
	Mick Smith > working at 36 c/t TODD Bell - saw 3 overpressure events on seal.				
	Injured coal mine worker 1				
	Injured coal mine worker 4				
	Injured coal mine worker 5				
	Injured coal mine worker 3				

Injured workers

Injured coal mine worker 2

- Additional injured - still way out



GROSVENOR COAL MINE
PRO-Mine Emergency Response System

Assessment of Response -	
Topic	Comments
Notification of Emergency	
Activation of ERT	
Resources available (equipment and personnel)	
Equipment condition	
Communication during response	
Information provided during response	
Additional support provided	
Adequate skills/training to respond	
Other	

Critical Issues	Recommended Corrective Actions	By Whom



GROSVENOR COAL MINE
PRO-Mine Emergency Response System

Employee Assistance Scheme provided/offered to ERT Member YES NO

Details:

ERT Member Signature:

Copy sent to Manager for review & actioning (circle): YES/NO	Additional information attached (circle): YES/NO Details:	Enablon Incident No:
Debriefing Officer Signature:		