



GROSVENOR COAL MINE
PRO-Mine Emergency Response System

20.1.12. Appendix 11: ERT Debrief Form

Debrief Officer:

Role:

Date/Time of Debrief:

Date of Emergency: 6.5.20	Time Emergency Started:	Time Emergency Finished:
Type of Emergency: Injured Coal mine workers		
Location of Emergency: Long Wall face		
Name: Todd Bell		
Crew/Department: C Vent		
Work location: 35ct M/LD4		
Role in ERT: assisted four injured Coal mine workers		
Time Notified of Emergency:		
How Notified: Notified by deputy and other coal mine workers		
Time Your Response Started: immediately		
No. of responders in ERT: 3		
Breakdown of Emergency		
Time	Description	
	heard and felt pressure push flexi and it pushed it out and sucked back in and pushed back out with more more force than the first then sucked back in and pushed back out with less force than the first	
	Then headed out of cutthrough heading out by to crib room got to 35 35ct and seen injured Coal mine workers then assisted them to surface	



GROSVENOR COAL MINE
PRO-Mine Emergency Response System

Assessment of Response -	
Topic	Comments
Notification of Emergency	
Activation of ERT	
Resources available (equipment and personnel)	
Equipment condition	
Communication during response	
Information provided during response	
Additional support provided	
Adequate skills/training to respond	
Other	

Critical Issues	Recommended Corrective Actions	By Whom



GROSVENOR COAL MINE
PRO-Mine Emergency Response System

Employee Assistance Scheme provided/offered to ERT Member YES NO

Details:

ERT Member Signature:

Copy sent to Manager for review & actioning (circle): YES/NO	Additional information attached (circle): YES/NO Details:	Enablon Incident No:
Debriefing Officer Signature:		

